








日付	工事内容	施工本数	累計施工本数
12/8	杭施工	1	1
12/15	杭施工	1	2
12/22	杭施工	1	3
12/29	杭施工	1	4
1/5	杭施工	1	5
1/12	杭施工	1	6
1/19	杭施工	1	7
1/26	杭施工	1	8
2/2	杭施工	1	9
2/9	杭施工	1	10
2/16	杭施工	1	11
2/23	杭施工	1	12
3/2	杭施工	1	13
3/9	杭施工	1	14
3/16	杭施工	1	15
3/23	杭施工	1	16
3/30	杭施工	1	17
4/6	杭施工	1	18
4/13	杭施工	1	19
4/20	杭施工	1	20
4/27	杭施工	1	21
5/4	杭施工	1	22
5/11	杭施工	1	23
5/18	杭施工	1	24
5/25	杭施工	1	25
6/1	杭施工	1	26




BV1-2の水質モニタリング




観測孔位置図








日付	工事内容	施工本数	累計施工本数



BV1-3の水質モニタリング




BV2-1の水質モニタリング



日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			
4/20			
4/27			
5/4			
5/11			
5/18			
5/25			
6/1			










BV2-3の水質モニタリング



日付	工事内容	施工本数	累計施工本数








各孔のEC(mS/m)



日付	工事内容	施工本数	累計施工本数








観測孔位置図

各孔のORP(mV)




日付	工事内容	施工本数	累計施工本数

各孔のDO(mg/L)










日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			
4/20			
4/27			
5/4			
5/11			
5/18			
5/25			
6/1			










観測孔位置図

各孔の水温(°C)



日付	工事内容	施工本数	累計施工本数
12/8			0
12/15			0
12/22			0
12/29			0
1/5			0
1/12			0
1/19			0
1/26			0
2/2			0
2/9			0
2/16			0
2/23			0
3/2			0
3/9			0
3/16			0
3/23			0
3/30			0
4/6			0
4/13			0
4/20			0
4/27			0
5/4			0
5/11			0
5/18			0
5/25			0
6/1			85

各孔の濁度(FTU)









日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			
4/20			
4/27			
5/4			
5/11			
5/18			
5/25			
6/1			



観測孔位置図

各孔の水位(m)



観測孔位置図

日付	工事内容	施工本数	累計施工本数
12/8			
12/15			
12/22			
12/29			
1/5			
1/12			
1/19			
1/26			
2/2			
2/9			
2/16			
2/23			
3/2			
3/9			
3/16			
3/23			
3/30			
4/6			
4/13			
4/20			
4/27			
5/4			
5/11			
5/18			
5/25			
6/1			